

# VEHICLE INSPECTION REPORT

**DG16EDC**

## Man TGS 26.360

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	08/04/2016	VIN	WMA18SZZ5GP072228	Axle Combi	6x2
Year	2016	Body Style	Curtainside	Steering Combi	Rear-Lift Steer
Mileage	308,671 Km Warranted	MOT Due	31/12/2025	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	DAY CAB	Rear Doors	Barn
Colour	BLUE	Gearbox	MANUAL		

\*WARNING LIGHT ON DASH\* FORKLIFT BRACKET, SERVICE SCHEDULE LISTING AVAILABLE

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Cruise control
- Park assist camera
- Radio/CD
- Front electric windows
- Cloth seat trim

## Photos











THE UNLADEN WEIGHT OF THE VEHICLE PLUS THE KERB WEIGHT TO CALCULATE THE PAYLOAD


MANUFACTURE	MODEL	WEIGHT
Bevan Mounty	M5 25.3LT	2585kg
Bevan Mounty	M7 24.3	2310kg
Bevan Mounty	M7 24.4	2430kg
Bevan Mounty	M7 24.3LT	2845kg
Bevan Mounty	M8 25.3LT	2940kg

Bevan GROUP





Condition Check



Damage Photos



1: Dash Warning Lights  
Displayed  
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault		